

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

AS227
West
1/4-1/2
0.351 mi.
1851 ft.

ON ROADWAY
HART PLACE AND CROSEY AVE
BROOKLYN, NY

NY Spills **S110308233**
N/A

Site 4 of 7 in cluster AS

Relative:
Higher

Actual:
9 ft.

SPILLS:

Name: ON ROADWAY
Address: HART PLACE AND CROSEY AVE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 1000827 / 2010-06-21
Facility ID: 1000827
Facility Type: ER
DER Facility ID: 388420
Site ID: 433510
DEC Region: 2
Spill Cause: Unknown
Spill Class: C4
SWIS: 2401
Spill Date: 2010-04-21
Investigator: Con Ed Unassigned
Referred To: Not reported
Reported to Dept: 2010-04-21
CID: Not reported
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2010-04-21
Spill Record Last Update: 2010-06-21
Spiller Name: Not reported
Spiller Company: UNK
Spiller Address: Not reported
Spiller Company: 999
Contact Name: ERT
DEC Memo: "06/21/10 - See eDocs for Con Ed report detailing cleanup and closure. "
Remarks: "cleanup pending - unknown source"

All Materials:

Site ID: 433510
Operable Unit ID: 1184394
Operable Unit: 01
Material ID: 2178657
Material Code: 0017A
Material Name: PCB oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .06
Units: G
Recovered: Not reported
Oxygenate: Not reported